

## APPENDIX 3

**Photograph 1: Capping of old landfill (2010)**



**Photograph 2: Side liner of Stage 1A (2004 – 2005)**



**Photograph 3: Side liner of Stage 1A (2004 – 2005)**





**Photograph 4: Benching to sides of Stage 3A (2013)**



**Photograph 5: Benching to sides of Stage 3A (2013)**





**Photograph 6: HDPE liner construction Stage 1A (2004)**



**Photograph 7: GCL and HDPE liner construction Stage 1A (2004)**



**Photograph 8: Mixing bentonite for GCL liner joins Stage 1A (2004)**




**Photograph 9: HDPE liner welding Stage 1A (2004)**






**Photograph 10: HDPE liner quality assurance marks Stage 3A (2013)**



**Photograph 11: Placement of sand protection layer Stage 1A (2004)**



**Photograph 12: Placement of sand protection layer Stage 1A (2004)**



**Photograph 13: Electric dipole integrity testing Stage 3A (2013)**





**Photograph 14: Placement of first layer of waste Stage 1A (2004)**



**Photograph 15: Leachate pond**






**Photograph 16: Stage 2 liner completed**



**Photograph 17: Stage 2 liner completed**





**Photograph 18: Capping at edge of Stage 1A**



**Photograph 19: Tatana Drain looking upstream**





**Photograph 20: View across Tatana property looking north-east**



Photograph 21: Tatana Drain looking downstream





**Photograph 22: Cattle in Tatana Drain**



**Photograph 23: Oblique aerial photograph taken prior to 2002**



